Purulia & Kharagpur Transmission Company Limited

I. AC Transmission Line Outage Details for the month of September 2021

	Outage	Restoration		Duration	of Outage Attributable	to	Reason of	%
	Outage	Restoration	Inter-State	Duration	System constraint/	10	Reason of	70
Element Name			Transmission	Others	Natural calamity/	Deemed Available	Outage	Availability
Lienen Hune	Date & Time	Date & Time	Licensee	Onicis	Militancy	Declined Available	Outage	Availability
			Hrs:Min	Hrs:Min	Hrs:Min	Hrs:Min		
400 KV D/C New Panchi-New Dyrulia								
400 KV,D/C New Ranchi-New Purulia Line: CKT-1	07-09-2021	07-09-2021	0:37	0.00	0:00		Line tripped due to Y-Phase to B-Phase Fault.	
							Line tripped due to DT received at New Ranchi S/S. Only Line portion belongs to PKTCL.	99.982%
400 KV,D/C New Ranchi-New Purulia Line: CKT-1	09-09-2021	09-09-2021	0:00	2:48	0.00	0:00	S/S.	
							Only Line portion belongs to PKTCL.	
	l	İ						
μ		l						

Schedule I

II. Elements where restoration time has exceeded the standards specified in Regulation 5 (b) for the month of September 2021								

Element Name	Restoration time as specified in Regulation 5 (b) (in days)	Actual restoration time (in days)			
Nil	Nil	Nil			
Nil	Nil	Nil			
Nil	Nil	Nil			

III. Details of compensation paid by the inter-State transmission licensee for the month of September 2021

Element Name	Violation of F	Regulation 5(a)	Violat	ion of Regulation 5(b)	
	%	Actual % Availability	Restoration time Actual restoration		Compensation paid (in Rs)
	Availability prescribed		prescribed time		
	-		(in days)	(in days)	
Nil	Nil	Nil	Nil	Nil	Nil
Nil	Nil	Nil	Nil	Nil	Nil
		Nil			

Schedule III