

Name of Transmission Licensee :- Parbati Koldam Transmission Company Limited

I. AC Transmission Line Outage Details for the month of July 2021

Schedule I

Element Name	Outage	Restoration	Duration of Outage Attributable to				Reason of Outage	% Availability
	Date Time	Date Time	Inter-State Transmission Licensee	Others	System constraint/ Natural calamity/ Militancy	Deemed Available		
			Hrs:Min	Hrs:Min	Hrs:Min	Hrs:Min		
400kV D/C Koldam-Ludhiana Ckt-02	08/07/2021 19:52	08/07/2021 21:43	00:00	00:00	01:51	00:00	Due to inclement weather conditions and lightning strike leading to forest fire which causes huge smoke creating conductive path from R Phase to Earth Fault led to transient tripping of the line. Photographic and video evidence confirming the same is attached for your reference.	99.93%

II. Elements where restoration time has exceeded the standards specified in Regulation 5 (b) for the month of July 2021

Schedule II

Element Name	Restoration time as specified in Regulation 5 (b) (in days)	Actual restoration time (in days)
NIL	-	
-	-	
-	-	

III. Details of compensation paid by the inter-State transmission licensee for the month of July 2021

Schedule III

Element Name	Violation of Regulation 5(a)		Violation of Regulation 5(b)				Compensation paid (in Rs)	
	% Availability prescribed	Actual % Availability	Restoration time prescribed (in days)		Actual restoration time (in days)			
NIL	-	-	-	-				-
-	-	-	-	-				-
<b>Total</b>								