

Parbati Koldam Transmission Company Limited

I. AC Transmission Line Outage Details for the month of October 2023

Schedule I

Element Name	Outage		Restoration		Duration of Outage Attributable to			Reason of Outage	% Availability
	Date Time	Date Time	Inter-State Transmission Licensee	Others	System constraint/ Natural calamity/ Militancy	Deemed Available			
			Hrs:Min	Hrs:Min	Hrs:Min	Hrs:Min			
400kV Koldam-Ludhiana Ckt 2	01-10-2023 10:21	01-10-2023 17:34	7:13	0:00	0:00	0:00	Planned shutdown taken by PKTCL for defect rectification work.	99.62%	
400kV Koldam-Ludhiana Ckt 2	21-10-2023 13:19	21-10-2023 15:41	2:22	0:00	0:00	0:00	The line tripped off due to B-Ph to earth fault.		
400 KV Parbati_2(NH)-Sainj(HP) (PKTCL) Ckt-1	09-10-2023 19:06	14-10-2023 16:45	0:00:00	0:00:00	0:00:00	117:39:00	Planned shutdown taken by NHPC for Civil work at Parbati2.		
400 KV Parbati_2(NH)-Parbati Pooling Banala(PG) (PKTCL) Ckt-1	09-10-2023 19:07	14-10-2023 16:43	0:00:00	0:00:00	0:00:00	117:36:00	Planned shutdown taken by NHPC for Civil work at Parbati2.		
400kV Koldam-Ludhiana Ckt 1	18/10/2023 02:37	18/10/2023 05:54	0:00	0:00	0:00	3:17	Line was hand tripped as per RLDC instruction due to Voltage Regulation.		
400kV Koldam-Ludhiana Ckt 2	19/10/2023 02:36	19/10/2023 05:29	0:00	0:00	0:00	2:53	Line was hand tripped as per RLDC instruction due to Voltage Regulation.		
400kV Koldam-Ludhiana Ckt 1	20/10/2023 00:34	20/10/2023 06:34	0:00	0:00	0:00	6:00	Line was hand tripped as per RLDC instruction due to Voltage Regulation.		
400kV Koldam-Ludhiana Ckt 1	22/10/2023 02:49	22/10/2023 06:28	0:00	0:00	0:00	3:39	Line was hand tripped as per RLDC instruction due to Voltage Regulation.		
400kV Koldam-Ludhiana Ckt 2	23/10/2023 00:39	23/10/2023 07:12	0:00	0:00	0:00	6:33	Line was hand tripped as per RLDC instruction due to Voltage Regulation.		
400kV Koldam-Ludhiana Ckt 2	25/10/2023 00:34	25/10/2023 06:15	0:00	0:00	0:00	5:41	Line was hand tripped as per RLDC instruction due to Voltage Regulation.		
400kV Koldam-Ludhiana Ckt 1	25/10/2023 22:48	26/10/2023 05:14	0:00	0:00	0:00	6:26	Line was hand tripped as per RLDC instruction due to Voltage Regulation.		
400kV Koldam-Ludhiana Ckt 2	26/10/2023 22:44	27/10/2023 05:57	0:00	0:00	0:00	7:13	Line was hand tripped as per RLDC instruction due to Voltage Regulation.		
400kV Koldam-Ludhiana Ckt 2	28/10/2023 00:37	28/10/2023 06:13	0:00	0:00	0:00	5:36	Line was hand tripped as per RLDC instruction due to Voltage Regulation.		
400kV Koldam-Ludhiana Ckt 1	29/10/2023 21:58	30/10/2023 06:03	0:00	0:00	0:00	8:05	Line was hand tripped as per RLDC instruction due to Voltage Regulation.		
400kV Koldam-Ludhiana Ckt 2	30/10/2023 22:31	31/10/2023 05:38	0:00	0:00	0:00	7:07	Line was hand tripped as per RLDC instruction due to Voltage Regulation.		

Parbati Koldam Transmission Company Limited

II. Elements where restoration time has exceeded the standards specified in Regulation 5 (b) for the month of October 2023

Schedule II

Element Name	Restoration time as specified in Regulation 5 (b) (in days)	Actual restoration time (in days)
NIL	NIL	NIL
NIL	NIL	NIL
NIL	NIL	NIL

III. Details of compensation paid by the inter-State transmission licensee for the month of October 2023

Schedule III

Element Name	Violation of Regulation		Violation of Regulation 5(b)		Compensation paid (in Rs)
	% Availability prescribed	Actual % Availability	Restoration time prescribed (in days)	Actual restoration time (in days)	
NIL	NIL	NIL	NIL	NIL	NIL
NIL	NIL	NIL	NIL	NIL	NIL
Total					NIL