	tutage Details for the month							Schedule I
	Outage	Restoration		n of Outag	e Attributable to			
			Inter-State Transmission		System constraint/	Deemed Available		
Element Name	p	y	Licensee	Others	Natural	2 s vanable	Reason of Outage	% Availability
	Date Time	Date Time			calamity/			,
					Militancy			
			Hrs:Min	Hrs:Min	Hrs:Min	Hrs:Min	Shut down tolers has prevent	
							Shut down taken by PKTCL to readjust Phase to Phase clearance	
400 kV Koldam Ludhiana-II	29/04/2021 10:35	29/04/2021 23:19	12:44	00:00	00:00	00:00	b/w conductors of gantry/slack span at Ludhiana end. (D-3) for	
			1				prevention of phase to phase fault	
							during inclament weather conditions Shut Down taken for testing of the	
400 kV Parbati III-Banala Pooling Station	04/04/2021 11:14	04/04/2021 15:37	00:00	04:23	00:00	04:23	Bus coupler CB at Parbati-3.	
400 kV Parbati III-Sainj HEP	04/04/2021 11:27	04/04/2021 16:07	00:00	04:40	00:00	04:40	Shut Down taken For testing of the Bus coupler CB at Parbati-3.	
400 kV Koldam Ludhiana-I	06/04/2021 13:09	06/04/2021 20:29	00:00	07:20	00:00	07:20	OVER VOLTAGE (MANUALLY OPEN)	
			00:00	07:20	00:00	07:20		
							Line Tripped due to Phase to Phase fault Y-B fault as per PMU. Direct	
							Trip (DT) received at Banala from Koldam due to CB opens at Koldam	
400 kV Banala Koldam	06/04/2021 23:30	07/04/2021 00:40					on system high voltage and send trip	
							command to Banala. Communication received from RTAMC Jammu	
			00:00	01:10	00:00	01:10	attached as Annexure II	
400 kV Banala Koldam	07/04/2021 00:40	07/04/2021 06:00	00:00	05:20	00:00	05:20	OVER VOLTAGE (MANUALLY OPEN)	
			00.00	33.20	00.00	33.20	Shut Down taken by NHPC for	
400 kV Parbati II-Banala Pooling Station	26/04/2021 11:24	26/04/2021 18:43					maintenance work of Potyard and painting of Parbati-II HEP Power	
			00:00	07:19	00:00	07:19	House (OCC-182)	
400 M/ Darbari II Sai-1 1/52	06/04/0001 11 01	06/04/0001 16:00					Shut Down taken by NHPC for maintenance work of Potyard and	
400 kV Parbati II-Sainj HEP	26/04/2021 11:24	26/04/2021 19:13	00:00	07:49	00:00	07:49	painting of Parbati-II HEP Power House (OCC-182)	
			00:00	07:49	00:00	07:49	Shut Down taken by NHPC for	
400 kV Parbati II-Banala Pooling Station	27/04/2021 09:48	27/04/2021 19:14					maintenance work of Potyard and painting of Parbati-II HEP Power	
			00:00	09:26	00:00	09:26	House (OCC-182)	
							Shut Down taken by NHPC for maintenance work of Potyard and	
400 kV Parbati II-Sainj HEP	27/04/2021 09:53	27/04/2021 19:32					painting of Parbati-II HEP Power	
			00:00	09:39	00:00	09:39	House (OCC-182) Shut Down taken by NHPC for	
400 kV Parbati II-Sainj HEP	28/04/2021 09:11	28/04/2021 19:07					maintenance work of Potyard and	
			00:00	09:56	00:00	09:56	painting of Parbati-II HEP Power House (OCC-182)	
							Shut Down taken by NHPC for	
400 kV Parbati II-Banala Pooling Station	28/04/2021 09:16	28/04/2021 18:51					maintenance work of Potyard and painting of Parbati-II HEP Power	
			00:00	09:35	00:00	09:35	House (OCC-182) Shut Down taken by NHPC for	
400 kV Parbati II-Banala Pooling Station	29/04/2021 08:59	29/04/2021 19:31					maintenance work of Potyard and	
	25,04/2021 00:09	22/07/2021 17:31	00:00	10:32	00:00	10:32	painting of Parbati-II HEP Power House (OCC-182)	
			00.00	20.52	00.00	10.32	Shut Down taken by NHPC for	
400 kV Parbati II-Sainj HEP	29/04/2021 09:14	29/04/2021 19:50					maintenance work of Potyard and painting of Parbati-II HEP Power	
			00:00	10:36	00:00	10:36	House (OCC-182)	
400 M Darkery							Shut Down taken for XLPE cables link box got damaged at Parbati-3.	
400 kV Parbati III-Banala Pooling Station	29/04/2021 13:17	29/04/2021 16:47	00:00	03:30	00:00	03:30	S/D taken for replacement of the	
			00:00	03.30	00.00	05.30	Shut Down taken by NHPC for	99.12%
400 kV Parbati II-Banala Pooling Station	30/04/2021 09:14	30/04/2021 18:58					maintenance work of Potyard and painting of Parbati-II HEP Power	
			00:00	09:44	00:00	09:44	House (OCC-182)	
							Shut Down taken by NHPC for maintenance work of Potyard and	
400 kV Parbati II-Sainj HEP	30/04/2021 09:30	30/04/2021 19:08	00.00	00.20	00.00	00.22	painting of Parbati-II HEP Power	
			00:00	09:38	00:00	09:38	House (OCC-182) Line was returened for charging at	
400 kV Koldam Ludhiana-II	07/04/2021 01:56	07/04/2021 06:01					01:56 but was not charged due to voltage regulations issues. Mail	
The second secon	,0.,2021 01.00	,0,,2021 00.01					Pertaining for the same is attached as	
			00:00	00:00	04:05	04:05	Annexure-IV	
							Line Tripped due to Phase to phase fault R-Y . Line tripped due to	
							inclament weather conditions. Many	
							transmission elements of other stakeholders in nearby vicinity of	
400 kV Koldam Ludhiana-II	06/04/2021 20:19	06/04/2021 22:40					transmission line also got tripped due to incalment weather conditions	
							(NRLDC Daily outage report	
							attached as annexure). Newspaper cutting confirming inclament	
			00:00	02:21	00:00	02:21	weather conditions are also attached.	
			55.00		55.50	52.21		
							Line Tripped due to Phase to earth	
							fault R-N, Zone-1, Dist. 45.405km, Fault current 5.428kA from Banala.	
							Line tripped due to inclament	
400 kV Banala Nalagarh	06/04/2021 21:55	06/04/2021 22:48					weather conditions. Many transmission elements of other	
							stakeholders in nearby vicinity of transmission line also got tripped due	
							to incalment weather conditions (NRLDC Daily outage report	
							attached as annexure). Newspaper	
			00:00	00:53	00:00	00:53	cutting confirming inclament weather conditions are also attached.	
			22.00	23.33	00.00	30.33		
							Line Tripped due to Phase to earth fault R-N, Dist. 32.2km, Fault	
							current 6.22kA from Koldam. Line tripped due to inclament weather	
							conditions. Many transmission	
400 kV Koldam Ludhiana-II	07/04/2021 00:36	07/04/2021 01:56					elements of other stakeholders in nearby vicinity of transmission line	
							also got tripped due to incalment weather conditions (NRLDC Daily	
							outage report attached as annexure).	
							Newspaper cutting confirming inclament weather conditions are	
			00:00	01:20	00:00	01:20	also attached.	
			23.00		22.00	12.20	LineTripped due to R-Y fault due to	
ADD IAL Worldow Loudh's "							heavy storm ,lighting and inclement weather condition. F.D = 0km from	
400 kV Koldam Ludhiana-II	16/04/2021 14:51	16/04/2021 18:40					Ludhiana end. F.C: 19 kA. Line tripped due to inclament weather	
			00:00	03:49	00:00	03:49	tripped due to inclament weather conditions.	

$II.\ Elements\ where\ restoration\ time\ has\ exceeded\ the\ standards\ specified\ in\ Regulation\ 5\ (b)\ for\ the\ month\ of\ May\ 2021$

Element Name	Restoration time as specified in Regulation 5 (b) (in days)	Actual restoration time (in days)
NIL	-	
-	•	
-		

Schedule III

$III.\ Details\ of\ compensation\ paid\ by\ the\ inter-State\ transmission\ licensee\ for\ the\ month\ of\ May\ 2021$

Element Name	Violation of R	Violation of Regulation 5(b)						
	%	Actual % Availability	Restoration time		Actual restoration		Compensation paid (in Rs)	
	Availability prescribed		prescribed		time			
			(in days)		(in days)			
NIL	-	-	-	-				-
-	-	-	-	-				-
Total								