

Raichur Sholapur Transmission Company Private Limited

I. AC Transmission Line Outage Details for the month of August 2023

Schedule I

Element Name	Outage		Restoration		Duration of Outage Attributable to				Reason of Outage	%
	Date	Time	Date	Time	Inter-State Transmission Licensee Hrs:Min	Others Hrs:Min	System constraint/ Natural calamity/ Militancy Hrs:Min	Deemed Available Hrs:Min		
RAICHUR - SHOLAPUR II	08-08-2023	11:06:00	08-08-2023	12:18:00	00:00:00	01:12:00	00:00:00	0:00:00	RSTCPL taken emergency shutdown to facilitate insulator replacement work at Tower No. 198. The line was shut down at 11:06 AM. However, due to an isolator closing issue at Raichur SS , PTW (Permit to Work) for the same was issued at 12:18 PM. Kindly please consider additional outage hours into other account. We have enclosed the email communication for your reference. Shutdown Code - 1171	99.47%
RAICHUR - SHOLAPUR II	08-08-2023	12:18:00	08-08-2023	16:15:00	03:57:00	00:00:00	00:00:00	0:00:00	RSTCPL taken the emergency shutdown for insulator replacement work at Tower No. 198. PTW for the same was issued at 12:18Hrs. Charging clearance was given at 16:09Hrs and charging code was received at 16:15Hrs and line was finally charged at 19:09Hrs. The delay in charging, following the receipt of the charging code was due to Isolator closing issue at Raichur end as per the information received from PGCIL enclosed here with the email copy. Charging code of SRLDC-1223 had been cancelled due to Isolator alignment issue at Raichur end. While only the line portion falls under the jurisdiction of RSTCPL, the terminal equipment of the bay is owned by PGCIL.	
RAICHUR - SHOLAPUR II	08-08-2023	16:15:00	08-08-2023	19:09:00	00:00:00	02:54:00	00:00:00	0:00:00	Charging code of SRLDC-1223 had been cancelled due to Isolator alignment issue at Raichur end, enclosed here with the email copy. While only the line portion falls under the jurisdiction of RSTCPL, the terminal equipment of the bay is owned by PGCIL. Request to please consider addition outage hours into other account. Charging Code - 1264	

Raichur Sholapur Transmission Company Private Limited

II. Elements where restoration time has exceeded the standards specified in Regulation 5 (b) for the month of August 2023

Schedule II

Element Name	Restoration time as specified in Regulation 5 (b) (in days)	Actual restoration time (in days)
Nil	Nil	Nil
Nil	Nil	Nil
Nil	Nil	Nil

III. Details of compensation paid by the inter-State transmission licensee for the month of August 2023

Schedule III

Element Name	Violation of Regulation		Violation of Regulation 5(b)		Compensation paid (in Rs)
	% Availability prescribed	Actual % Availability	Restoration time prescribed (in days)	Actual restoration time (in days)	
Nil	Nil	Nil	Nil	Nil	Nil
Nil	Nil	Nil	Nil	Nil	Nil
Total					Nil