

Raichur Sholapur Transmission Company Private Limited

I. AC Transmission Line Outage Details for the month of October 2023

Schedule I

Element Name	Outage		Restoration		Duration of Outage Attributable to				Reason of Outage	% Availability
	Date	Time	Date	Time	Inter-State Transmission Licensee Hrs:Min	Others Hrs:Min	System constraint/ Natural calamity/ Militancy Hrs:Min	Deemed Available Hrs:Min		
RAICHUR - SHOLAPUR II	10-10-2023	09:57:00	10-10-2023	11:09:00	00:00:00	01:12:00	00:00:00	0:00:00	RSTCPL taken shutdown for AMP Work. The line was shut down at 09:57 AM. PTW (Permit to Work) for the same was issued at 11:09 AM due to unknown reason. Kindly please consider additional outage hours into other account. We have enclosed the email communication for your reference. Shutdown Code : 986 Charging Code :	98.35%
RAICHUR - SHOLAPUR II	10-10-2023	11:09:00	10-10-2023	17:12:00	06:03:00	00:00:00	00:00:00	0:00:00	RSTCPL taken the shutdown for AMP Work. PTW for the same was issued at 11:09Hrs. Charging clearance was given at 17:04Hrs and charging code was received at 17:12Hrs and line was finally charged at 18:40Hrs. The delay in charging, following the receipt of the charging code was due to unknown reason enclosed here with the email copy. Shutdown Code : Charging Code : 1050	
RAICHUR - SHOLAPUR II	10-10-2023	17:12:00	10-10-2023	18:40:00	00:00:00	01:28:00	00:00:00	0:00:00	RSTCPL given the charging clearance at 17:04Hrs and charging code was received at 17:12Hrs and line was finally charged at 18:40Hrs. The delay in charging, following the receipt of the charging code was due to unknown reason enclosed here with the email copy. Kindly please consider additional outage hours into other account. We have enclosed the email communication for your reference.	
RAICHUR - SHOLAPUR II	13-10-2023	09:44:00	13-10-2023	11:00:00	00:00:00	01:16:00	00:00:00	0:00:00	RSTCPL taken shutdown for AMP Work. The line was shut down at 09:44 AM. PTW (Permit to Work) for the same was issued at 11:00 AM due to unknown reason. Kindly please consider additional outage hours into other account. We have enclosed the email communication for your reference. Shutdown Code : 1455 Charging Code :	
RAICHUR - SHOLAPUR II	13-10-2023	11:00:00	13-10-2023	17:10:00	06:10:00	00:00:00	00:00:00	0:00:00	RSTCPL taken the shutdown for AMP Work. PTW for the same was issued at 11:00Hrs. Charging clearance was given at 17:10Hrs and charging code was received at 18:08Hrs and line was finally charged at 18:50Hrs. The delay in receipt of charging code due to grid constraint enclosed here with the email copy. Shutdown Code : Charging Code : 1502	
RAICHUR - SHOLAPUR II	13-10-2023	17:10:00	13-10-2023	18:50:00	00:00:00	00:00:00	00:00:00	1:40:00	RSTCPL given the charging clearance at 17:10Hrs and charging code was received at 18:08Hrs and line was finally charged at 18:50Hrs. The delay in receipt of charging code due to grid constraint enclosed here with the email copy. Kindly please consider additional outage hours into Deemed account. We have enclosed the email communication for your reference.	

**Raichur Sholapur Transmission Company Private Limited**

**II. Elements where restoration time has exceeded the standards specified in Regulation 5 (b) for the month of October 2023**

**Schedule II**

Element Name	Restoration time as specified in Regulation 5 (b) (in days)	Actual restoration time (in days)
Nil	Nil	Nil
Nil	Nil	Nil
Nil	Nil	Nil

**III. Details of compensation paid by the inter-State transmission licensee for the month of October 2023**

**Schedule III**

Element Name	Violation of Regulation		Violation of Regulation 5(b)		Compensation paid (in Rs)
	% Availability prescribed	Actual % Availability	Restoration time prescribed (in days)	Actual restoration time (in days)	
Nil	Nil	Nil	Nil	Nil	Nil
Nil	Nil	Nil	Nil	Nil	Nil
<b>Total</b>					Nil