RAPP Transmission Company Limited

I. AC Transmission Line Outage Details for the month of June 2023

	Ou	tage	Resto	ration		Duration of Outage Attributable to		Reason of	%	
Element Name	Date	Time	Date	Time	Inter-State Transmission Licensee Hrs:Min	Others Hrs:Min	System constraint/ Natural calamity/ Militancy Hrs:Min	Deemed Available Hrs:Min	Outage	Availability
400kV RAPP-Sujalpur Ckt-1	02-06-2023	9:58:00	02-06-2023	19:21:00	9:23	0:00	0:00	0:00	RTCL taken the shutdown for Line maintenance work at 09:58Hrs, PTW was received at 11:01Hrs. Charging clearance was given at 18:51Hrs and charging code was received at 18:59Hrs. RTCL considering additional 30min from the charging clearance time into RTCL account. Kindly consider addition outage period under Others category, line was charged from Sujalpur SS at 20:09Hrs and during synchronisation DT send from RAPP SS and Line tripped. Enclosed here with the email communication for your reference.	98.73%
400kV RAPP-Sujalpur Ckt-1	02-06-2023	19:21:00	02-06-2023	20:11:00	0:00	0:50	0:00	0:00	Charging clearance was given at 18:51Hrs and charging code was received at 18:59Hrs. RTCL considering additional 30min from the charging clearance time into RTCL account. Kindly consider addition outage period under Others category, line was charged from Sujalpur SS at 20:09Hrs and during synchronisation DT send from RAPP SS and Line tripped at 20:11Hrs. Enclosed here with the email communication for your reference.	
400kV RAPP-Sujalpur Ckt-1	02-06-2023	20:11:00	03-06-2023	1:05:00	0:00	4:54	0:00	0:00	Line tripped while synchronizing from RAPP end, line tripped due to DT sent from RAPP SS to Shujalpur SS. Enclosed here with the email communication for your reference.	
400kV RAPP-Sujalpur Ckt-2	03-06-2023	9:46:00	03-06-2023	18:08:00	8:22	0:00	0:00	0:00	RTCL taken the shutdown for Line maintenance work at 09:46Hrs, PTW was received at 10:38Hrs. Charging clearance was given at 18:08Hrs and RTAMC cancelled the opportunity shutdown code at 19:12Hrs. Delayed in charging due to the opportunity shutdown availed by PGCIL. Enclosed here with the email communication for your reference.	
400kV RAPP-Sujalpur Ckt-2	03-06-2023	18:08:00	03-06-2023	20:25:00	0:00	2:17	0:00	0:00	RTCL given the charging clearance at 18:08Hrs and PGCIL returned the opportunity shutdown at 19:12hrs and line was finally charged at 20:25Hrs. Delayed in charging was due to cancellation of opportunity shutdown code and also due to unknown reason at RAPP SS. Enclosed here with the email copy.	

Schedule I

RAPP Transmission Company Limited

II. Elements where restoration time has exceeded the standards specified in Regulation 5 (b) for the month of June 2023

Schedule II

	Restoration time as specified in	Actual restoration time		
Element Name	Regulation 5 (b)	(in days)		
	(in days)			
Nil	Nil	Nil		
Nil	Nil	Nil		
Nil	Nil	Nil		

III. Details of compensation paid by the inter-State transmission licensee for the month of June 2023

Schedule III

Element Name	violation of Regulation		Violation of R		
	%	Actual %	Restoration time	Actual restoration	Compensation paid (in Rs)
	Availability prescribed		prescribed	time	
			(in days)	(in days)	
Nil	Nil	Nil	Nil	Nil	Nil
Nil	Nil	Nil	Nil	Nil	Nil
	Nil				