

RAPP Transmission Company Limited

I. AC Transmission Line Outage Details for the month of May 2023

Schedule I

Element Name	Outage		Restoration		Duration of Outage Attributable to				Reason of	%
	Date	Time	Date	Time	Inter-State Transmission Licensee Hrs:Min	Others Hrs:Min	System constraint/ Natural calamity/ Militancy Hrs:Min	Deemed Available Hrs:Min	Outage	Availability
400kV RAPP-Sujalpur Ckt-1					0:00	0:00	0:00	0:00	No tripping / Outages in this month	100.00%
400kV RAPP-Sujalpur Ckt-2	26-05-2023	1:20:00	26-05-2023	21:37:00	0:00	20:17	0:00	0:00	Line Tripped due to TEED Protection Operated at RAPP SS and DT Received at Shujalpur end. Only line portion belongs to RTCL. Tripping has been converted into shutdown by RAPP for the jumper clamp tightness work at RAPP end switchyard.	

RAPP Transmission Company Limited

II. Elements where restoration time has exceeded the standards specified in Regulation 5 (b) for the month of May 2023

Schedule II

Element Name	Restoration time as specified in Regulation 5 (b) (in days)	Actual restoration time (in days)
Nil	Nil	Nil
Nil	Nil	Nil
Nil	Nil	Nil

III. Details of compensation paid by the inter-State transmission licensee for the month of May 2023

Schedule III

Element Name	violation of Regulation 5(a)		Violation of Regulation 5(b)		Compensation paid (in Rs)
	% Availability prescribed	Actual % Availability	Restoration time prescribed (in days)	Actual restoration time (in days)	
Nil	Nil	Nil	Nil	Nil	Nil
Nil	Nil	Nil	Nil	Nil	Nil
Total					Nil

