Odisha Generation Phase-II Transmission Limited

I. AC Transmission Line Outage Details for the month of July 2021

	Outage	Restoration	tion Duration of Outage Attributable to			to	Reason of	96
Element Name		Date & Time	Inter-State Transmission Licensee	Others	System constraint/ Natural calamity/ Militancy	Deemed Available	Outage	Availability
			Hrs:Min	Hrs:Min	Hrs:Min	Hrs:Min		
65kV D/C Jharsuguda(Sundargarh)- Raipur pool CKT-1	01-07-2021	02-07-2021	0:00	0.00	0:00	35:17	Under outage since last month due to Voltage Regulation as per RLDC Instruction. Charged in this month	
65kV D/C Jharsuguda(Sundargarh)- Raipur pool CKT-2	02-07-2021	13-07-2021	0:00	0.00	0.00	274:20	Line taken out of service due to Voltage Regulation as per RLDC Instruction.	100%
65kV D/C Jharsuguda(Sundargarh)- Raipur pool CKT-1	13-07-2021	26-07-2021	0:00	0:00	0:00	308:35	Line taken out of service due to Voltage Regulation as per RLDC Instruction.	100%
65kV D/C Jharsuguda(Sundargarh)- Raipur pool CKT-2	26-07-2021	01-08-2021	0:00	0:00	0:00	122:58	Line taken out of service due to Voltage Regulation as per RLDC Instruction.still not chareed in this month.	
	1						1	

Schedule I

II. Elements where restoration time has exceeded the standards specified in Regulation 5 (b) for the month of July 2021

	Restoration time as specified in	Actual restoration time		
Element Name	Regulation 5 (b)	(in days)		
	(in days)			
Nil	Nil	Nil		
Nil	Nil	Nil		
Nil	Nil	Nil		

III. Details of compensation paid by the inter-State transmission licensee for the month of July 2021

Element Name Violation of Regulation 5(a)			Violat	ion of Regulation 5(b)		
	%	Actual %	Restoration time Actual restoration		Compensation paid (in Rs)	
	Availability prescribed	Availability	prescribed			
	-		(in days)	(in days)		
Nil	Nil	Nil	Nil	Nil	Nil	
Nil	Nil	Nil	Nil	Nil	Nil	
		Nil				

Schedule III