Odisha Generation Phase-II Transmission Limited

I. AC Transmission Line Outage Details for the month of September 2021 $\,$

Element Name		Outage	Restoration		Duration	of Outage Attributable	to	Reason of	%
Element Name				Inter-State					,,,
Licensee	Element Name	Data & Time	Data & Time		Others	Natural calamity/	Deemed Available	Outage	Availability
1.656V D/C sharequale@undergurh-		Date & Time	Date & Time			Militancy		_	
Religious pool CRT-2				Hrs:Min	Hrs:Min	Hrs:Min	Hrs:Min		
1.69-2021 21-0	765kV D/C Jharsuguda(Sundargarh)- Rainur nool CKT-2	02-09-2021	13-09-2021	0:00	0.00	0.00	252:45	Line Hand tripped as per RLDC instruction	
Tripping happened at 04-48Hrs and information for the same was received from the period CRT 2 21-09-2021 21-09-2021 0.00 2.00 2.00 2.00 2.00 2.00 2.00	765kV D/C Jharsuguda(Sundargarh)-	13-09-2021	21-09-2021	0:00	0.00	0:00	186:02	Line Hand tripped as per RLDC instruction	
Phase fault,	765kV D/C Jharsuguda(Sundargarh)- Raipur pool CKT-2	21-09-2021	21-09-2021	0:00	2:07	0:00	0:00	Tripping happened at 04:48Hrs and information for the same was received from ERLDC at 06:55hrs, hence the outage time will be consider under Others account, attached	
Charging code was received at 11:12hrs, line Charging code was recei	76SkV D/C Jharsuguda(Sundargarh)- Raipur pool CKT-2	21-09-2021	21-09-2021	0:00	0:00	3:33	0:00	Phase fault, due to inclement weather condition. Attached here with the newspaper cutting. Charging clearance was given at 10:28Hrs and charging code was received at 11:12hrs,	100%
Raipur pod CKT-2 due to voltage regulation. Line Hand tripped as per RLDC instruction Raipur pod CKT-3 due to voltage regulation. 178.6W I/O. Janrauguda Sundargarhi- 23-09-2021 01-10-2021 0-00 0-00 178.20 due to voltage regulation. due to voltage regulation.	765kV D/C Jharsuguda(Sundargarh)- Raipur pool CKT-2	21-09-2021	21-09-2021	0:00	1:48	0:00	0:00	charging code was received at 11:12hrs, line was charged at 12:16hrs due to high volatge at harsuguda S/S as per the information recived from ERLDC, attached here with the email copy for reference.	
765kV D)C. Amerusgoda(Sundargurh)- 23-09-2021 01-10-2021 0:00 0:00 0:00 178-20 Line Hand tripped as per RLDC instruction due to voltage regulation.	765kV D/C Jharsuguda(Sundargarh)- Raipur pool CKT-2	21-09-2021	23-09-2021	0:00	0:00	0:00	42:29	Line Hand tripped as per RLDC instruction due to voltage regulation.	
	765kV D/C Jharsuguda(Sundargarh)- Raipur pool CKT-1	23-09-2021	01-10-2021	0:00	0:00	0:00	178:20	Line Hand tripped as per RLDC instruction due to voltage regulation.	
									· ·
		ļ							
		l	l						
	<u> </u>	1							

Schedule I

II. Elements where restoration time has exceeded the standards specified in Regulation 5 (b) for the month of September 2021

	Restoration time as specified in	Actual restoration time			
Element Name	Regulation 5 (b)	(in days)			
	(in days)				
Nil	Nil	Nil			
Nil	Nil	Nil			
Nil	Nil	Nil			

III. Details of compensation paid by the inter-State transmission licensee for the month of September 2021

Element Name	Violation of Regulation 5(a)		Violat	ion of Regulation 5(b)		
	% Actual %		Restoration time Actual restoration		Compensation paid (in Rs)	
	Availability prescribed	Availability	prescribed time		Compensation paid (in res)	
			(in days)	(in days)		
Nil	Nil	Nil	Nil	Nil	Nil	
Nil	Nil	Nil	Nil	Nil	Nil	
	•	Nil				

Schedule III