	Ou	tage	Resto	oration	Duration of Outage Attributable to		Reason of	%		
Element Name	Date	Time	Date	Time	Licensee	Others	System constraint/ Natural calamity/ Militancy	Deemed Available	Outage	Availability
400kV maheshwaram[PG]-Mehboob nagger(TS) Line-2	04-09-2021	11:18:00	04-09-2021	17:21:00	Hrs:Min	Hrs:Min	Hrs:Min	Hrs:Min	Planned shutdown taken for carrying out general maintenance and equipment testing, shutdown availed by TSTRANSCO Shutdown code: 314 Charging Code: 350	
400kV maheshwaram(PG)-Mehboob nagger(TS) Line-2	05-09-2021	03:11:00	16-09-2021	10:11:00	0:00	0:00	0:00	271:00	Line Hand Trigord as yet RDC instruction. On what per egulation. Shutdown code: 376 Charging Code: 1396 Woltage at Mehbooh nagur during taking out of service: 4222W m during taking out of service: 4262W m during charging time: 4104W voltage at Mehbooh nagur during charging time: 4406W	99.83%
	1	-		-			<b>-</b>			
	1						<u> </u>			
							1			
	1						1			
	1						<u> </u>			
	1	-	-	-			-			-
	1						<u> </u>			
	1	-	-	-			-			-
	1	-	-	-			<u> </u>			-
							1			

## Schedule II

Schedule III

## II. Elements where restoration time has exceeded the standards specified in Regulation 5 (b) for the month of September 2021

Element Name	Restoration time as specified in Regulation 5 (b) (in days)	Actual restoration time (in days)			
Nil	Nil	Nil			
Nil	Nil	Nil			
Nil	Nil	Nil			

## $III.\ Details\ of\ compensation\ paid\ by\ the\ inter-State\ transmission\ licensee\ for\ the\ month\ of\ September\ 2021$

Element Name	Violation of F	Regulation 5(a)	Violati	ion of Regulation 5(b)		
	%	Actual %	Restoration time Actual restoration		Compensation paid (in Rs)	
	Availability prescribed	Availability	prescribed	time		
			(in days)	(in days)		
Nil	Nil	Nil	Nil	Nil	Nil	
Nil	Nil	Nil	Nil	Nil	Nil	
	Nil					