	Outage		Restoration		Duration of Outage Attributable to				Reason of	%
Element Name	Date	Time	Date	Time	Inter-State Transmission Licensee	Others	System constraint/ Natural calamity/ Militancy	Deemed Available	Outage	Availability
					Hrs:Min	Hrs:Min	Hrs:Min	Hrs:Min		
400kV RAPP-Sujalpur Ckt-1	11-07-2021	12:30:00	11-07-2021	18:46:00	0:00	6:16	0:00	0:00	RAPP Taken Force shutdown due to line CVT Y-phase clamp loosen rectification work. Only Line portion belongs to RTCL.	
400kV RAPP-Sujalpur Ckt-2	14-07-2021	19:14:00	14-07-2021	19:14:00	0:00	0:00	0:00	0:00	Line A/R successful due to transient Y- Phase to Ground Fault.	100%
400kV RAPP-Sujalpur Ckt-2	16-07-2021	13:17:00	16-07-2021	20:07:00	0:00	6:50	0:00	0:00	RAPP Taken force shutdown for attending connection job of damaged Moose conductor of CT 27 B pole terminal connector at Rapp end. Only Line portion belongs to RTCL.	
	1	1	-		 	 	 			
	+									
	1	1								
	1	1				ļ	-			
	-									
	1	1	-		 	 	 			
	+	 								
	1	1			<u> </u>	1	<u> </u>			

Schedule II

$II.\ Elements\ where\ restoration\ time\ has\ exceeded\ the\ standards\ specified\ in\ Regulation\ 5\ (b)\ for\ the\ month\ of\ July\ 2021$

Element Name	Restoration time as specified in Regulation 5 (b) (in days)	Actual restoration time (in days)		
Nil	Nil	Nil		
Nil	Nil	Nil		
Nil	Nil	Nil		

Schedule III

III. Details of compensation paid by the inter-State transmission licensee for the month of July 2021 $\,$

Element Name	ement Name Violation of Regulation 5(a)			ion of Regulation 5(b)	
	%	Actual %	Restoration time	Actual restoration	Compensation paid (in Rs)
	Availability prescribed	Availability	prescribed	time	Compensation paid (in Rs)
			(in days)	(in days)	
Nil	Nil	Nil	Nil	Nil	Nil
Nil	Nil	Nil	Nil	Nil	Nil
	Nil				