

East North Interconnection Company Limited

I. AC Transmission Line Outage Details for the month of MAY 2023

Schedule I

Element Name	Outage	Restoration	Duration of Outage Attributable to				Reason of	%
	Date & Time	Date & Time	Inter-State Transmission Licensee Hrs:Min	Others Hrs:Min	System constraint/ Natural calamity/ Militancy Hrs:Min	Deemed Available Hrs:Min	Outage	Availability
400 kv (Quad) D/C Bongaigaon - Alipurduar line CKT- 1(BNG- ALIP #1)	02-05-2023	02-05-2023	10:25:00	0:00:00	0:00:00	0:00:00	ENICL taken the shutdown for attending the conductor stand cut at location 22A/1.	99.282%
400 kv (Quad) D/C Bongaigaon - Alipurduar line CKT- 2(BNG- ALIP #2)	03-05-2023	03-05-2023	9:14:00	0:00:00	0:00:00	0:00:00	ENICL taken the shutdown for attending the conductor stand cut at location 30/0.	
400 kv (Quad) D/C Alipurduar - Siliguri line CKT- 1(ALIP- SLG #1)	05-05-2023	05-05-2023	9:55:00	0:00:00	0:00:00	0:00:00	ENICL taken the shutdown for Pre-Monsoon AMP Work.	
400 kv (Quad) D/C Alipurduar - Siliguri line CKT- 2(ALIP- SLG #2)	06-05-2023	06-05-2023	7:08:00	0:00:00	0:00:00	0:00:00	ENICL taken the shutdown for Pre-Monsoon AMP Work.	
400 kv (Quad) D/C Alipurduar - Siliguri line CKT- 2(ALIP- SLG #2)	25-05-2023	25-05-2023	0:00:00	0:00:00	0:00:00	11:35:00	PGCIL taken the shutdown for Firmware upgradation of P444 Relay at Binaguri End. Only line portion belongs to ENICL.	
400 kv (Quad) D/C Bongaigaon - Alipurduar line CKT- 2(BNG- ALIP #2)	31-05-2023	31-05-2023	8:14:00	0:00:00	0:00:00	0:00:00	ENICL taken the emergency shutdown for Dead end rectification work. Charging clearance was given at 18:46Hrs and charging code for the same was received at 18:51Hrs and line was finally charged at 19:48Hrs. Delay in charging was due to unknown reason at both end substation, only line portion belongs to ENICL.	
400 kv (Quad) D/C Bongaigaon - Alipurduar line CKT- 2(BNG- ALIP #2)	31-05-2023	31-05-2023	0:00:00	0:57:00	0:00:00	0:00:00	Charging clearance was given at 18:46Hrs and charging code for the same was received at 18:51Hrs and line was finally charged at 19:48Hrs. Delay in charging was due to unknown reason at both end substation, only line portion belongs to ENICL.	
400 kv (Quad) D/C Purnia-Biharshrif Line CKT-1 (NPRN-BSF#1)			0:00:00	0:00:00	0:00:00	0:00:00	No Tripping/outage in this month	
400 kv (Quad) D/C Purnia-Biharshrif Line CKT-2 (NPRN-BSF# 2)			0:00:00	0:00:00	0:00:00	0:00:00	No Tripping/outage in this month	

East North Interconnection Company Limited

II. Elements where restoration time has exceeded the standards specified in Regulation 5 (b) for the month of MAY 2023

Schedule II

Element Name	Restoration time as specified in Regulation 5 (b) (in days)	Actual restoration time (in days)
Nil	Nil	Nil
Nil	Nil	Nil
Nil	Nil	Nil

III. Details of compensation paid by the inter-State transmission licensee for the month of MAY 2023

Schedule III

Element Name	Violation of Regulation		Violation of Regulation 5(b)		Compensation paid (in Rs)
	% Availability prescribed	Actual % Availability	Restoration time Prescribed (in days)	Actual restoration time (in days)	
Nil	Nil	Nil	Nil	Nil	Nil
Nil	Nil	Nil	Nil	Nil	Nil
Total					Nil