Khargone Transmission Limited

I. AC Transmission Line Outage Details for the month of JUL 2023

Sah.	~d++1	^ T	

Outage		Restoration		Duration of Outage Attributable to			Reason of	%		
					Inter-State		System constraint/			
Element Name Date	Date Time	Time	Date	Time	Transmission	Others	Natural calamity/	Deemed Available	Outage	Availability
		e Date Time	Time	Licensee		Militancy				
				Hrs:Min	Hrs:Min	Hrs:Min	Hrs:Min			
765/400kV Khandwa-KTL-ICT-1 at Khandwa SS	10-07-2023	9:55:00	10-07-2023	21:35:00	11:40	0:00	0:00	0:00	KTL taken the shutdown for AMP Work	
765kV Khandwa-KTL-BR-1 at Khandwa SS	16-07-2023	11:41:00	16-07-2023	16:26:00	4:45	0:00	0:00	0:00	KTL taken the emergency shutdown to attend the oil leakages	99.84%
705KV Kilalidwa-KTL-BR-1 at Kilalidwa 55	55 10-07-2025 11:41:00 10-07-2025 10:20:00 4:40 0:00 0:00	0:00	of conservator tank for B-Phase.	99.0 1 70						
765kV Khandwa-KTL-BR-1 at Khandwa SS	22-07-2023	21:49:00	23-07-2023	0:16:00	2:27	0:00	0:00	0:00	Bus Reactor tripped due to Y-phase PRV-02 Operated.	

Khargone Transmission Limited

II. Elements where restoration time has exceeded the standards specified in Regulation 5 (b) for the month of JUL 2023

Schedule II

	Restoration time as specified in	Actual restoration time		
Element Name	Regulation 5 (b)	(in days)		
	(in days)			
Nil	Nil	Nil		
Nil	Nil	Nil		
Nil	Nil	Nil		

III. Details of compensation paid by the inter-State transmission licensee for the month of JUL 2023

Schedule III

Element Name	Violation of Regulation		Violation of R		
	%		Restoration time	Actual restoration	
	Availability prescribed	Actual % Availability	prescribed	time	Compensation paid (in Rs)
			(in days)	(in days)	
Ni1	Nil	Nil	Nil	Nil	Nil
Ni1	Nil	Nil	Nil	Nil	Nil
	Nil				