### Khargone Transmission Limited

## I. AC Transmission Line Outage Details for the month of MAY 2023

_										
	Out	age	Resto	ration		Duration of Outa	ge Attributable to		Reason of	%
Element Name	Date	Time	Date	Time	Inter-State Transmission Licensee Hrs:Min	Others Hrs:Min	System constraint/ Natural calamity/ Militancy Hrs:Min	Deemed Available Hrs:Min	Outage	Availability
765KV-Dhule-Khandwa-Sterlite-2	30-05-2023	15:09:00	30-05-2023	16:58:00	0:00	0:00	1:49	0:00	Line tripped on transient Y-Phase to Earth Fault due to inclement weather condition and also due to foreign material came in contact with the line which causes tripping, Attached here with the newspaper cutting and photograph of foreign material hanging in the earthwire for your reference. This incident is beyond the control of licensee.	99.96%
400kV Khandwa-Khargone(NTPC) Line	31-05-2023	10:00:00	31-05-2023	20:15:00	0:00	0:00	0:00	10:15	PGCIL taken the shutdown for AMP work. Only LILO portion belongs to KTL. Remaining portion belongs to PGCIL.	

Schedule I

## **Khargone Transmission Limited**

# II. Elements where restoration time has exceeded the standards specified in Regulation 5 (b) for the month of MAY 2023

Schedule II

	Restoration time as specified in	Actual restoration time
Element Name	Regulation 5 (b)	(in days)
	(in days)	
Nil	Nil	Nil
Nil	Nil	Nil
Nil	Nil	Nil

# III. Details of compensation paid by the inter-State transmission licensee for the month of MAY 2023

Schedule III

Element Name	Violation of Regulation		Violation of Regulation 5(b)  Restoration time Actual restoration		-
	Availability prescribed	Actual % Availability	prescribed		Compensation paid (in Rs)
			(in days)	(in days)	
Nil	Nil	Nil	Nil	Nil	Nil
Nil	Nil	Nil	Nil	Nil	Nil
	Nil				